



Protection against humidity

## Valuable data, in real time!

**PROPASECARD** is a stiff card with reversible reading spots of the relative humidity (HR), "**cobalt-dichloride free**", changing the colour from blue to rose when a relative humidity level has been exceeded.

**PROPASECARD** has to be put into the packaging of the product that you want to control and it is available in several versions.

**PROPASECARD** can indicate low relative humidity levels down to a 5% HR or high levels up to a 95% HR, according to the application and necessity.

It provides visual proof of the level of HR in an environment and/or packing.

If **PROPASECARD** indicates high humidity levels, users know that the desiccant must be replaced and the product checked.

It is normally used with desiccants in any application where humidity is at a critical point that can affect the manufactured product.

The humidity indicator **PROPASECARD** is easy to use and quickly readable. Spots are blue in absence of moisture and they turn to pink at the reaching of different indicated humidity levels.

## To solve problems caused by:







Internal moisture





## **proposec**ard®



**Indicators with viewing window: PROPASECARD with viewing window** can be put in protective bags and caps too, in order to control the relative humidity rate inside the packaging looking from outside.

## Main applications:

- Electronics
- Military components
- Optical instruments
- Packing
- Automotive sector
- Diagnostics
- Museums and works of art



